

Thomas E. DeLafosse
Vice President
Salco Products, Regulatory Compliance Group
1409 Edenbridge Drive
Alcoa, TN 37701-2264
630.512.7595 Cell
tom.delafosse@salcoproducts.com

To: Distribution List

Subject: March 2023 AAR Circular Letter Summary

The March 2023 summary includes the (9) circular letters issued during the month.

This document provides a summary of each Association of American Railroads ("AAR") circular letter issued during the previous month. A circular letter provides information of general applicability to the railroad industry, including proposed and final rules, standards, and recommended practices. Circulars are a fee-based service provided by AAR's Transportation Technology Center, Incorporated ("TTCI") located in Pueblo, Colorado. You may sign up to receive AAR circular letters online. If you need further assistance with access to circulars, please send any future questions and issues to Pubs@aar.com.

The Field Manual of the AAR Interchange Rules, Rule 1, b. (11), requires maintaining a copy of each "mandatory circular letter" that revises an "Interchange Rule" or the "Manual of Standards and Recommended Practices." For your convenience, this document identifies mandatory circular letters. For those circulars that propose or implement final changes to an existing rule, standard, or recommended practice, this document provides an impact statement to car owners, lessors, mechanical shops, and railroad operations.

The following matrix identifies the AAR circular letter number, a summary of the circular, any effective date of a rule, standard, or recommended practice, any comment due date, an impact statement, and to the extent it applies, if the circular letter is mandatory.

If you have any questions, please contact Tom DeLafosse at 630.512.7595 or tom.delafosse@salcoproducts.com.

Circular No.	Subject and Summary	Impact Statement			
	Implemented Changes, Effective the Date of Circular				
C-14109 Mar. 6, 2023	Subject: Informational Circular, Car Repair Facility Labor Rate – Effective April 1, 2023.	Car Type: Freight Car Owner: Possibly			
2023	Summary: The Car Repair Facility Labor Rate, effective April 1, 2023 is \$187.57, an increase of \$0.57 (or 0.30%) from the labor rate calculated for January 1, 2023.	Repair Shop: No			
	Implementation Date: This will be reflected in the April 1, 2023 release of the AAR Office Manual.	Comments: New independent labor agreements were signed in the first quarter 2023 and immediately implemented retroactive wage increases. The new agreements are like the national wage increases structure along with three \$1,000 lump sum payments; however, they vary by contract.			

C-14111 Mar. 9, 2023	Subject: Implementation of Circular No. 42-P, General Rules Governing the Loading of Carload Shipments of Commodities in Closed Car (DP&FC). Summary: The AAR's Damage Prevention & Freight Claim Committee (DP&FC) has approved changes to Circular No. 42-P, General Rules Governing the Loading of Carload Shipments of Commodities in Closed Car (DP&FC). Implementation Date: This revision to Circular 42, General Rules Governing the Loading of Carload Shipments of Commodities in Closed Car (DP&FC) are now implemented and effective immediately.	Car Type: Railroads Car Owner: No Repair Shop: No Comments: Circular 42-P (Supersedes Circular No. 42-O).
	Changes Pending 30-Day (Generally) Comment Period fro	om Date of Circular
C-14110 Mar. 8, 2023	Subject: Solicitation of Comments for Revisions to MSRP Section H-II, Roller Bearing Manual, Standard S-723, Inner Ring Inspection. Additional inspection requirements.	Car Type: Freight Car Owner: No
	Summary: this circular letter is to solicit comments for revisions proposed to MSRP Section H-II, Roller Bearing Manual, S-723, Inner Ring Inspection, regarding inspection of the inner ring in both directions. Implementation Date: All comments, relevant to the proposed revisions, received within 30 days of the issuance of this circular will be considered by the WABL Committee.	Repair Shop: No, Bearing shops, yes Comments: The proposed inspection of the inner ring in both directions has a maximum one-year industry cost of \$4.35 million and 15-year net present cost of \$35.15 million.
C-14113 Mar. 14, 2023	Subject: Solicitation of Comments for Revisions to MSRP Section C, Car Construction Fundamentals and Details, Standard S-910 and Specifications M-800 and M-801, edits relative to marking of autoracks and certain hopper cars. Summary: This circular letter is to solicit comments for the following revisions: S-910, M-800, and M-801. Refer to the circular for the attachments noting the proposed revisions. Implementation Date: All comments relevant to the proposed revisions received within 30 days of the issuance of this circular will be considered by the AAR Equipment Engineering Committee	Car Type: Freight Car Owner: Possible Repair Shop: Yes for S-910 Autorack height clarence. Comments: Refer to the circular for the proposed revised changes.

C-14116	Subject: Solicitation of Comments for revisions to MSRP E	Car Type: Freight
Mar. 15, 2023	Brakes and Brake Equipment, S-4027, Automated Single Car Test Equipment, Conventional Brake Equipment—Design and Performance Requirements. Data validation enhancements.	Car Owner: No
		Repair Shop: Yes
	Summary: This circular letter is to solicit comments for	
	revisions proposed to Section E, S-4027 Automated Single Car Test Equipment, Conventional Brake Equipment—Design	Comments: The changes are to enhance the accuracy and
	and Performance Requirements.	consistency of Automated Single
		Car Test Device test data to
	Implementation Date: All comments relevant to the	facilitate compliance with Federal
	proposed revisions received within 30 days of the issuance of	Railroad Administration
	this circular will be considered by the BSC prior to further action.	requirements.
	action.	
C-14114	Subject: Solicitation of Comments for Revisions to MSRP	Car Type: Freight
Mar. 15,	Section B, Freight Car Draft Components, Specification M-	
2023	921D Cushioning Devices, End-of-Car, Motor-Vehicle-Carrying. Addition of New Requirements.	Car Owner: No
	Carrying. Addition of New Requirements.	Repair Shop: No
	Summary: This circular letter is to solicit comments for	nopuli diseprind
	revisions proposed to MSRP Section B, Freight Car Draft	Comments: Interested parties
	Components, Specification M-921B Cushioning Devices, End-	should download the proposed
	of-Car, Motor-Vehicle-Carrying.	revised Specification M-921D for review and possible comment.
	Implementation Date: All comments relevant to the	review and possible comment.
	proposed revisions received within 30 days of the issuance of	
	this circular will be considered by the AAR Equipment	
	Engineering Committee.	
C-14117	Subject: Canadian Car Repair Facility Labor Rate – Effective	Car Type: Canadian RR's
Mar. 16,	April 1, 2023	
2023		Car Owner: Possibly
	Summary: The Canadian Car Repair Billing Labor Rate calculation for April 1, 2023 is \$242.94 CAD, an increase of	Panair Shan, No
	\$3.57 CAD from the calculation for January 1, 2023.	Repair Shop: No
	Total St.	Comments: For comparison
	Implementation Date: The change will be reflected in the	purposes, this converts to about
	April 1, 2023 release of the Canadian Price Master.	\$176.54 in U.S. dollars. The
		currency conversion factor used to calculate the Health & Welfare
		portions of the January 1
		Canadian Labor Rate was 1.3346.

General Information for the Industry				
C-14112	Subject: MSRP Section N, Specification M-951, Portable	Car Type: Railroads		
Mar. 9,	Bridge Plates for Multi-Level Auto Rack Cars.			
2023		Car Owner: No		
	Summary: This is an informational circular to allow the			
	industry time to prepare for changes to MSRP, Section N, M-	Repair Shop: No		
	951. The Specially Equipped Freight Car Committee is	Comments: Questions should be		
	implementing revisions to Specification M-951 that will be effective on 01/01/2025. This implementation will sunset any	directed to Mr. David Hendrixon,		
	low-capacity bridge plate, which is a bridge plate	Manager, Specially Equipped		
	manufactured prior to 2005.	Freight Car Committee at TTCI via		
		email at		
	Implementation Date: The addition with be to Specification	David_Hendrixon@aar.com		
	M-951, 8.5 Any bridge plate manufactured prior to 2005 will			
	no longer be approved for vehicle loading or unloading.			
C-14115	Subjects 2022 AAD AA 1002 Quality Assurance Auditor	Car Type, Industry Information		
Mar. 15,	Subject: 2023 AAR M-1003 Quality Assurance Auditor Training Class Schedule.	Car Type: Industry Information		
2023	Training class scriedule.	Car Owner: Possible		
2023	Summary: The Association of American Railroads (AAR)	Gai Gainer i ossibile		
	Quality Assurance Committee (QAC) has updated the	Repair Shop: Possible		
	schedule for the 2023 AAR M-1003 Quality Assurance			
	Training classes.	Comments: MxV Rail is offering a		
		full schedule of in person training		
	Implementation Date: Refer to this circular for locations and	classes throughout 2023.		
	dates.			